



# SEWER INSPECTION REPORT

**Purpose:**

GENERAL INSPECTION

**Recommended Action:**

RECOMMEND YEARLY MAINTENANCE/CLEANING

**Summary:**

MAIN SEWER DRAIN LINE WAS ACCESSED AT ROOF SEWER VENT. SEWER MAIN DRAIN IS MADE OF CAST IRON AND CLAY TO FOLLOW. UPON INSPECTION OF THE SEWER LINE SEWER DRAIN WAS IN SERVICEABLE CONDITION AT THE TIME OF THE INSPECTION WITH NO SIGNS OF ROOTS OR OBSTRUCTIONS.

<b>Location</b>	<b>Inspector</b>
18321 SATICOY ST. RESEDA CA 91335	Quality Care Home Inspections Mark Sandoval

02:20:43 PM / 03-13-2018

3/13/2018 2:20:43 PM

0' 0"



02:20:57 PM / 03-13-2018

3/13/2018 2:20:55 PM

77' 4"



77' 3"

3/13/2018 2:21:24 PM

61' 9"



61' 1"

3/13/2018 2:21:34 PM

56' 4"



55' 10"

3/13/2018 2:22:42 PM

38' 4"



38' 4"

02:22:58 PM / 03-13-2018

3/13/2018 2:22:59 PM

33' 8"



3/13/2018 2:23:22 PM

31' 9"



3/13/2018 2:23:58 PM

21' 1"

